

Tabelle 3

Ordinaten der Bahnunebenheiten bezüglich einer willkürlichen Basislinie, Bahn B
(mit großen Unebenheiten).

D = Entfernung vom Bahnbeginn in Metern.

L = Ordinaten des linken Bahnstreifens in cm.

R = Ordinaten des rechten Bahnstreifens in cm.

D	L	R	D	L	R	D	L	R	D	L	R
0-00	16-0	9-0	3-20	13-5	7-5	6-40	9-5	5-0	9-60	7-0	7-5
0-08	16-0	11-5	3-28	12-5	5-5	6-48	8-5	7-0	9-68	7-0	8-5
0-16	16-5	14-0	3-36	11-5	4-0	6-56	7-0	9-0	9-76	7-5	9-0
0-24	15-5	13-5	3-44	11-5	4-5	6-64	5-0	11-0	9-84	7-5	7-5
0-32	13-5	13-5	3-52	12-0	5-0	6-72	4-0	12-5	9-92	8-5	7-5
0-40	13-5	11-5	3-60	11-0	5-5	6-80	4-0	11-0	10-00	10-0	7-5
0-48	14-0	10-0	3-68	10-0	7-0	6-88	3-0	9-0	10-08	11-5	7-5
0-56	14-5	9-5	3-76	11-0	7-5	6-96	3-0	6-5	10-16	11-5	7-5
0-64	15-0	9-0	3-84	11-0	7-5	7-04	2-5	4-5	10-24	11-5	7-5
0-72	14-0	8-5	3-92	9-0	6-5	7-12	2-5	4-0	10-32	12-0	9-0
0-80	13-5	7-5	4-00	7-5	5-5	7-20	3-0	2-0	10-40	12-5	10-0
0-88	13-5	9-0	4-08	7-5	7-5	7-28	5-0	2-5	10-48	12-5	9-0
0-96	13-5	10-0	4-16	7-5	9-0	7-36	6-5	3-0	10-56	13-5	7-5
1-04	12-5	9-5	4-24	8-5	9-0	7-44	7-5	4-0	10-64	9-0	9-5
1-12	12-0	9-5	4-32	8-5	9-0	7-52	8-5	4-5	10-72	4-5	12-5
1-20	12-0	9-5	4-40	11-5	7-5	7-60	7-5	6-5	10-80	4-5	13-5
1-28	11-5	9-5	4-48	14-5	5-5	7-68	7-5	9-0	10-88	4-5	12-5
1-36	12-0	10-0	4-56	15-0	5-5	7-76	7-0	10-0	10-96	4-5	11-5
1-44	12-5	11-0	4-64	12-5	5-0	7-84	9-0	9-5	11-04	4-5	8-5
1-52	13-5	10-0	4-72	11-0	5-5	7-92	10-0	9-5	11-12	5-0	5-5
1-60	11-5	9-0	4-80	9-0	5-5	8-00	11-5	11-0	11-20	6-5	5-0
1-68	9-0	9-5	4-88	7-5	6-5	8-08	12-5	11-5	11-28	7-5	4-0
1-76	7-0	9-5	4-96	5-0	5-0	8-16	13-5	11-5	11-36	9-5	7-0
1-84	5-0	9-0	5-04	5-0	5-0	8-24	13-5	11-5	11-44	11-5	9-5
1-92	5-0	7-5	5-12	5-5	4-0	8-32	12-5	11-0	11-52	15-0	12-0
2-00	5-5	6-5	5-20	5-5	2-0	8-40	12-5	10-0	11-60	19-0	14-5
2-08	7-0	5-0	5-28	5-5	2-0	8-48	12-0	11-0	11-68	17-0	12-5
2-16	8-5	4-0	5-36	5-5	2-0	8-56	11-5	11-5	11-76	15-0	11-5
2-24	8-5	4-5	5-44	5-0	2-5	8-64	12-5	11-0	11-84	12-5	9-5
2-32	8-5	5-5	5-52	4-5	2-5	8-72	14-0	10-0	11-92	10-0	7-5
2-40	8-5	5-5	5-60	4-5	2-5	8-80	12-5	9-5	12-00	10-0	7-0
2-48	7-5	5-5	5-68	5-0	3-0	8-88	11-5	9-0	12-08	10-0	6-5
2-56	7-5	6-5	5-76	4-5	4-0	8-96	11-0	7-5	12-16	9-0	5-5
2-64	7-5	7-5	5-84	4-5	5-0	9-04	11-0	7-0	12-24	9-5	5-5
2-72	9-5	8-5	5-92	4-5	4-5	9-12	10-0	4-5	12-32	11-5	6-5
2-80	11-5	9-0	6-00	4-0	4-0	9-20	10-0	2-5	12-40	11-0	7-0
2-88	13-5	7-5	6-08	5-5	3-0	9-28	10-0	0-5	12-48	10-0	7-0
2-96	15-0	6-5	6-16	9-0	2-5	9-36	8-5	4-0	12-56	11-0	6-5
3-04	16-5	7-0	6-24	10-0	3-0	9-44	6-5	5-0	12-64	11-5	6-5
3-12	15-0	7-5	6-32	10-0	4-0	9-52	6-5	6-5	12-72	10-0	7-5

Tabelle 3
1. Fortsetzung

D	L	R	D	L	R	D	L	R	D	L	R
12-80	9-0	9-5	16-40	11-0	9-0	20-00	10-0	12-0	23-60	14-5	15-0
12-88	8-5	7-5	16-40	10-0	10-0	20-08	10-0	12-0	23-68	16-5	15-0
12-96	7-5	5-5	16-56	10-0	9-5	20-16	11-0	12-0	23-76	18-5	14-5
13-04	8-5	6-5	16-64	9-5	9-5	20-24	11-5	12-0	23-84	18-5	14-5
13-12	9-0	7-0	16-72	11-5	11-5	20-32	12-5	11-5	23-92	18-0	15-0
13-20	9-5	5-5	16-80	14-5	14-0	20-40	13-5	11-0	24-00	19-0	13-5
13-28	10-0	5-0	16-88	15-0	15-0	20-48	14-5	10-0	24-08	19-0	11-5
13-36	11-5	5-0	16-96	16-0	14-5	20-56	15-0	9-5	24-16	16-0	11-5
13-44	13-5	5-0	17-04	16-0	14-5	20-64	16-5	10-0	24-24	12-5	12-0
13-52	14-0	6-5	17-12	15-0	12-5	20-72	18-0	11-0	24-32	12-5	12-5
13-60	14-5	7-5	17-20	14-5	10-0	20-80	18-0	11-0	24-40	11-5	16-0
13-68	15-0	9-0	17-28	15-0	11-0	20-88	17-0	11-0	24-48	11-5	16-0
13-76	14-0	8-5	17-36	16-0	13-5	20-96	12-5	10-0	24-56	10-0	14-0
13-84	11-5	7-5	17-44	16-0	14-0	21-04	10-0	9-5	24-64	8-5	12-5
13-92	10-0	9-0	17-52	16-5	14-5	21-12	12-0	10-0	24-72	7-5	11-5
14-00	9-5	10-0	17-60	15-0	15-0	21-20	12-5	11-0	24-80	7-5	11-0
14-08	9-0	9-5	17-68	13-5	16-5	21-28	13-5	10-0	24-88	9-5	10-0
14-16	8-5	9-0	17-76	13-5	15-0	21-36	14-0	10-0	24-96	11-5	10-0
14-24	9-0	7-0	17-84	13-5	14-5	21-44	14-5	11-0	25-04	11-5	7-5
14-32	9-5	5-0	17-92	12-5	14-5	21-52	16-0	11-5	25-12	11-5	5-5
14-40	5-5	4-5	18-00	11-5	14-0	21-60	17-0	11-5	25-20	14-0	5-0
14-48	2-5	4-0	18-08	11-5	13-5	21-68	16-5	12-0	25-28	16-5	4-5
14-56	4-0	3-0	18-16	12-0	13-5	21-76	16-5	12-0	25-36	15-0	6-5
14-64	5-0	2-5	18-24	12-5	12-0	21-84	16-0	12-0	25-44	14-0	7-5
14-72	5-5	4-5	18-32	14-0	10-0	21-92	15-0	11-5	25-52	12-0	7-5
14-80	5-5	4-5	18-40	16-0	10-0	22-00	15-0	12-0	25-60	10-0	7-0
14-88	7-5	5-5	18-48	14-5	10-0	22-08	14-5	12-5	25-68	9-0	7-0
14-96	9-0	7-0	18-56	13-5	10-0	22-16	15-0	12-5	25-76	7-5	7-5
15-04	11-0	7-5	18-64	12-5	9-5	22-24	15-0	12-5	25-84	9-0	8-5
15-12	13-5	9-0	18-72	12-5	9-0	22-32	14-0	14-0	25-92	9-0	6-5
15-20	12-0	9-5	18-80	11-5	8-5	22-40	12-5	16-0	26-00	7-0	4-5
15-28	10-0	10-0	18-88	9-5	8-5	22-48	13-5	14-0	26-08	4-5	3-0
15-36	9-5	10-0	18-96	10-0	9-0	22-56	14-0	12-5	26-16	1-5	1-5
15-44	10-0	8-5	19-04	11-0	11-5	22-64	13-5	12-5	26-24	1-5	2-0
15-52	11-5	6-5	19-12	11-0	10-0	22-72	12-5	12-5	26-32	3-0	1-5
15-60	11-0	5-0	19-20	11-5	9-5	22-80	14-5	13-5	26-40	4-0	4-0
15-68	10-0	4-0	19-28	12-5	8-5	22-88	16-0	15-0	26-48	5-0	5-0
15-76	10-0	6-5	19-36	14-0	7-5	22-96	16-0	16-0	26-56	7-5	7-0
15-84	11-0	9-0	19-44	15-0	8-5	23-04	15-0	14-5	26-64	10-0	9-0
15-92	11-5	8-5	19-52	16-5	9-0	23-12	15-0	13-5	26-72	13-5	12-0
16-00	12-0	7-5	19-60	16-5	9-0	23-20	16-0	14-0	26-80	16-5	15-0
16-08	12-5	9-0	19-68	16-5	9-5	23-28	16-0	14-5	26-88	20-0	16-0
16-16	14-0	10-0	19-76	12-5	10-0	23-36	16-5	13-5	26-96	24-0	16-5
16-24	12-5	9-0	19-84	10-0	11-0	23-44	17-0	12-0	27-04	25-5	16-5
16-32	11-5	7-5	19-92	11-0	11-5	23-52	16-0	14-0	27-12	26-5	16-0

Tabelle 3
2. Fortsetzung

D	L	R	D	L	R	D	L	R	D	L	R
27-20	24-5	15-5	29-20	25-5	24-0	31-20	13-0	12-5	33-20	9-0	13-0
27-28	22-5	16-0	29-28	25-0	23-5	31-28	12-0	11-0	33-28	7-5	16-0
27-36	21-5	16-5	29-36	24-5	23-5	31-36	10-0	11-0	33-36	9-0	16-0
27-44	22-0	18-0	29-44	23-5	23-5	31-44	8-5	11-0	33-44	10-0	16-5
27-52	22-5	19-0	29-52	23-0	23-0	31-52	8-5	10-0	33-52	10-0	15-0
27-60	24-5	19-0	29-60	23-0	23-0	31-60	10-0	10-0	33-60	8-5	15-0
27-68	25-5	19-0	29-68	23-5	22-0	31-68	10-0	9-5	33-68	7-0	15-0
27-76	25-5	18-5	29-76	24-0	21-5	31-76	11-0	10-0	33-76	7-5	13-5
27-84	26-5	18-5	29-84	22-5	22-5	31-84	13-5	10-0	33-84	8-0	13-0
27-92	26-5	19-5	29-92	21-0	23-5	31-92	15-5	10-5	33-92	7-5	12-0
28-00	25-0	19-5	30-00	20-0	22-0	32-00	16-5	10-5	34-00	7-5	11-0
28-08	27-0	21-0	30-08	19-0	19-5	32-08	16-0	10-5	34-08	7-0	9-5
28-16	28-0	21-5	30-16	20-5	21-5	32-16	16-0	11-0	34-16	5-5	8-0
28-24	26-5	23-5	30-24	17-5	19-0	32-24	13-0	12-0	34-24	4-0	6-5
28-32	27-0	25-0	30-32	15-0	18-5	32-32	10-5	12-5	34-32	3-0	7-0
28-40	26-0	26-0	30-40	13-0	17-5	32-40	9-0	12-5	34-40	3-0	7-0
28-48	25-5	27-5	30-48	13-0	17-5	32-48	8-0	13-0	34-48	3-5	6-5
28-56	25-5	27-5	30-56	14-0	16-5	32-56	7-5	12-5	34-56	4-5	6-5
28-64	26-5	28-5	30-64	16-5	16-0	32-64	7-5	13-5	34-64	4-0	8-5
28-72	26-5	26-0	30-72	15-5	14-5	32-72	9-0	12-5	34-72	4-0	8-0
28-80	28-0	24-0	30-80	14-5	14-0	32-80	10-0	11-5	34-80	5-5	8-0
28-88	28-5	22-5	30-88	15-5	14-0	32-88	10-5	11-5	34-88	5-5	6-5
28-96	28-5	22-5	30-96	14-5	14-0	32-96	10-0	11-5	34-96	4-5	5-5
29-04	28-5	23-5	31-04	15-0	14-0	33-04	10-5	11-0	35-04	3-0	4-0
29-12	27-0	23-5	31-12	13-5	13-5	33-12	11-0	11-0			